Work Order ID	59957
---------------	-------

Packaging

Monday, June 21, 2010 9:02:11 AM



Page 1

Item ID: D4017-1 Accept Setup Start **Revision ID:** Stop Item Name: Rib **Start Date:** 6/21/2010 Start Qty: 1.00 **Cust Item ID: Required Date: 6/25/2010** Req'd Qty: 1.00 **Customer:** Reference: Run Start Process Plan: MK Date: (0-6 - 1) Tooling: **Approvals:** Date: Stop QC: Date: SPC (Y/N): Date: Sequence ID/ Operation Set Up/ Tool ID Tool # Plan Reject Accept Reject Insp. Work Center ID Description **Run Hours** Code Qty Qty Number Stamp Draw Nbr **Revision Nbr** OL AT IS D4017 В D10-06:21 100 0.00 Large Fab 0.00 Memo SAD 10-06-21 Large Fab 1- Cut tube as per dwg D4017 2- Drill hole as per dwg 3- Deburr and remove identify marks 110 QC5- Inspect part completeness to step on W/O 0.00 Memo Quality Control Identify as per dwg & Stock Location Basket 0.00 120 10.0621 Packaging 0.00 Memo

# **Dart Aerospace Ltd**

W/O:			WORK ORDER CHANGES									
DATE	STEP		PROCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector			
Part No	):		PAR #: Fault Category:	NCR	: Yes	No <b>DQ</b>	A:	_ Date: _				
	F	Resolution:	Disposition:	QA:	N/C (	Closed:		Date:				

NCR:		WORK ORDER NON-CONFORMANCE (NCR)											
- ** -		Description of NC		Corrective Action Section B	Verification	Ammunual							
DATE	STEP	STEP Description of NC Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector					
			٠										
			ļ										
				1									

#### Work Order ID 59957

Monday, June 21, 2010 9:02:11 AM



Page 2

Item ID:

D4017-1

Accept



Setup Start

**Revision ID:** 

Item Name: **Start Date:** 

Rib

6/21/2010

Start Qty: 1.00

Req'd Qty: 1.00



**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan: \_\_\_\_ Date:

Tooling:

Date:

Start Run

**Required Date: 6/25/2010** 

QC:

SPC (Y/N): Date:

Date:

Stop

Stop

Sequence ID/ **Work Center ID** 

Operation

Description

Memo

Set Up/ **Run Hours**  Tool ID

Tool # Plan Code

Accept Qty

Reject Reject Qty

Insp. Number Stamp

130

QC21- Final Inspection - Work Order Release

0.00

0.00

Quality Control

10/06/23 Hy M10-6-22

## **Dart Aerospace Ltd**

W/O:			WORK ORDER CHANGES											
DATE	STEP	PROC	PROCEDURE CHANGE					Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector				
					*				1 Tod Mg.					
				·										
						:								
Part No:		PAR #:	_ Fault Cat	egory:	NCR	:Yes N	Date:							
Resolution:			Dispositi	QA:	N/C Clo	sed:		Date: _						
NCR:		W	ORK ORI	DER NON-CONFORI	MANCE	(NCR)	)							
DATE	STEP	Description of NC				ection B			Approval	Approval				
DAIL	SIEP	Section A	Initial Chief Eng	Action Descriptio	n	Sign & Date	Sect	ion C	Chief Eng	QC Inspector				
			1											
					1									
									i	}				
					1									

### **Picklist Print**

Monday, June 21, 2010 9:02:10 AM

Work Order ID: 59957

Parent Item: D4017-1

Parent Item Name: Rib



**Start Date:** 6/21/2010

Required Date: 6/25/2010

10-06-21

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP RevA: new issue DD 09.11.26 verified by:EC per dwg RevA DD 10.03.06 verified by:EC

IPP Rev:B as IPP Rev:C as per dwg RevB

DD 10.04.16 verified by:EC


Component Item ID/	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304TS0.750W.049		Purchased	No			100	f	187.9102	4.73	4.97894	7		

304 SQ Tube .75x.75x.049W

Location	Loc Qty	Loc Code	
MAT	187.9101619		
113763	0		
114323	28.3020789		
114677	14.34201		
114835	145.266073		4.978742
MAT017	3.68448E-05		
114298	3.6845E-05		

## **Dart Aerospace Ltd**

W/O:		WORK ORDER CHANGES												
DATE	STEP	PRO	OCEDURE CHANGE			Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
				:										
Part No	•	PAR #:	Fault Categ	ory:	NCR: Yes	No <b>DQ</b>	<b>A</b> :	Date:						
Resolution:		esolution:	Disposition	_ QA: N/C (	QA: N/C Closed: Date:									
NCR:			WORK ORDE	R NON-CONFORM	ANCE (NC	R)								
DATE	OTED	Description of NC			ion B	Verific	cation	Approval	Approval					
DATE	STEP	. Section A	Initial Chief Eng	Action Description Chief Eng	Sign Dat	& Sect		Chief Eng	QC Inspector					
				·										
				•										
	•													
							<del></del>							
	-													
	1	1	1		ł			1	1					



W/O:			K ORDER CHANGES										
DATE	STEP	PRO	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector						
							_						
	}												
Part No		PAR #:	Fault Cate	egory:	_ NCR: Yes	No DQ	QA: Date:						
	R	esolution:	Disposition	on:	_ QA: N/C C	losed:		Date: _					
NCR:			WORK ORE	ER NON-CONFORMA	NCE (NC	R)							
DATE	CTED	Description of NC Section A		on B	Verific	ation	Approval	Approval					
DATE	STEP		Initial Chief Eng	Action Description Chief Eng	Sign Date	& Secti		Chief Eng	QC Inspector				